


Form Approved OMB No. 2010-0019 Approval Expires 12-31-89

90-89000 465 SEPA-OTS 0006226935



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Comprehensive Assessment Information Rule

REPORTING FORM

When completed, send this form to:

Document Processing Center Office of Toxic Substances, TS-790 U.S. Environmental Protection Agency 401 M Street, SW Washington, DC 20460 Attention: CAIR Reporting Office For Agency Use Only:

Date of Receipt:

Document
Control Number:

Docket Number:

General Offices/3M

3M Center St. Paul, Minnesota 55144-1000 612/733 1110 CONTAINS NO CBI

90-890000465

July 5, 1989

Certified Mail

Document Processing Center Office of Toxic Substances, TS-790 U.S. EPA 401 M St., S.W. Washington, D.C. 20460

Attn: CAIR Reporting Office

Dear Sir/Madam:

Attached is a completed CAIR Reporting form for 2,4/2,6. Toluene Diisocyanate, CAS No. 26471-62-5 for the 3M facility in Springfield, Missouri.

I would like to comment on one item. The Employer I.D. No. provided in questions 1.09 and 1.10 is the 9-digit IRS number used by the 3M Company. Since only 8 blocks are provided, the first digit is entered before the first block. This number was used on the advice of the CAIR "hotline".

We are not claiming any CBI in this report.

Sincerely,

Georjean L. Adams

Manager Regulatory Affairs

Peorlean Z. adams

Bldg. 225-4N-16

Tele: 612/737-4795

GLA:dm

Attachment

		SECTION 1 GENERAL MANUFACTURER, IMPORTER, AND PROCESSOR INFORMATION
PART	A G	ENERAL REPORTING INFORMATION
1.01	Thi	s Comprehensive Assessment Information Rule (CAIR) Reporting Form has been
CBI	com	pleted in response to the <u>Federal Register Notice of $[1]$ $[2]$ $[2]$ $[3]$ $[8]$ $[6]$ $[8]$ $[6]$</u>
[_]	a.	If a Chemical Abstracts Service Number (CAS No.) is provided in the Federal
		Register, list the CAS No $[0]2]6]4]7]1]-[6]2]-[5]$
	b.	If a chemical substance CAS No. is not provided in the <u>Federal Register</u> , list either (i) the chemical name, (ii) the mixture name, or (iii) the trade name of the chemical substance as provided in the <u>Federal Register</u> .
		(i) Chemical name as listed in the rule
		(ii) Name of mixture as listed in the rule
		(iii) Trade name as listed in the rule
	c.	If a chemical category is provided in the <u>Federal Register</u> , report the name of the category as listed in the rule, the chemical substance CAS No. you are reporting on which falls under the listed category, and the chemical name of the
		substance you are reporting on which falls under the listed category.
		Name of category as listed in the rule
		Name of category as listed in the rule
1.02	Ide	Name of category as listed in the rule CAS No. of chemical substance
		Name of category as listed in the rule CAS No. of chemical substance
CBI	Man	Name of category as listed in the rule CAS No. of chemical substance
CBI	Man Imp	Name of category as listed in the rule CAS No. of chemical substance
1.02 CBI	Man Imp Pro	Name of category as listed in the rule

in the above-listed Federal Register Notice? Yes		
No	1.03	Does the substance you are reporting on have an "x/p" designation associated with it in the above-listed Federal Register Notice?
No	CBI	Yes
under a trade name(s) different than that listed in the Register Notice? Circle the appropriate response. Yes No	l}	No
No	1.04	under a trade name(s) different than that listed in the Federal Register Notice?
b. Check the appropriate box below: [[_] CBI	
Provide the trade name(s) N/A [] You have chosen to report for your customers [] You have submitted the trade name(s) to EPA one day after the effective date of the rule in the Federal Register Notice under which you are reporting. 1.05 If you buy a trade name product and are reporting because you were notified of your reporting requirements by your trade name supplier, provide that trade name. [] Trade name N/A [] Is the trade name product a mixture? Circle the appropriate response. Yes No 1.06 Certification The person who is responsible for the completion of this form must sign the certification statement below: [] Thereby certify that, to the best of my knowledge and belief, all information entered on this form is complete and accurate." Georjean L. Adams		· ·
[] You have chosen to report for your customers [] You have submitted the trade name(s) to EPA one day after the effective date of the rule in the Pederal Register Notice under which you are reporting. 1.05 If you buy a trade name product and are reporting because you were notified of your reporting requirements by your trade name supplier, provide that trade name.		[] You have chosen to notify your customers of their reporting obligations
[] You have submitted the trade name(s) to EPA one day after the effective date of the rule in the Federal Register Notice under which you are reporting. 1.05 If you buy a trade name product and are reporting because you were notified of your reporting requirements by your trade name supplier, provide that trade name. CBI Trade name		Provide the trade name(s) N/A
reporting requirements by your trade name supplier, provide that trade name. N/A		You have submitted the trade name(s) to EPA one day after the effective date of the rule in the <u>Federal Register</u> Notice under which you are
Trade name		If you buy a trade name product and are reporting because you were notified of your reporting requirements by your trade name supplier, provide that trade name.
Is the trade name product a mixture? Circle the appropriate response. Yes	<u>CBI</u>	Trade name N/A
No	[_]	Is the trade name product a mixture? Circle the appropriate response.
1.06 Certification The person who is responsible for the completion of this form must sign the certification statement below: "I hereby certify that, to the best of my knowledge and belief, all information entered on this form is complete and accurate." Georjean L. Adams		Yes
sign the certification statement below: "I hereby certify that, to the best of my knowledge and belief, all information entered on this form is complete and accurate." Georjean L. Adams NAME Manager (612) 737 TELEPHONE TITLE		No
"I hereby certify that, to the best of my knowledge and belief, all information entered on this form is complete and accurate." Georjean L. Adams NAME Manager TITLE TELEPHONE TELEPHONE TELEPHONE TELEPHONE TITLE TELEPHONE TITLE		
Manager (612) 737 - 4795 TITLE TELEPHONE NO.		entered on this form is complete and accurate."
TITLE TELEPHONE NO.		Georjean L. Adams NAME Signature Column 7/7/89 DATE SIGNED
[_] Mark (X) this box if you attach a continuation sheet.		
	[_]	Mark (X) this box if you attach a continuation sheet.

1.07 <u>CBI</u> [_]	Exemptions From Reporting — If you have provided EPA or another Federal agency with the required information on a CAIR Reporting Form for the listed substance within the past 3 years, and this information is current, accurate, and complete for the time period specified in the rule, then sign the certification below. You are required to complete section 1 of this CAIR form and provide any information now required but not previously submitted. Provide a copy of any previous submissions along with your Section 1 submission.			
	information which I have not inc	pest of my knowledge and belief, a cluded in this CAIR Reporting Form and is current, accurate, and comp	has been submitted	
		SIGNATURE	DATE SIGNED	
	NAME	SIGNATURE	DATE STONES	
	TĪTLE	TELEPHONE NO.	DATE OF PREVIOUS SUBMISSION	
1.08 <u>CBI</u> []	certify that the following state those confidentiality claims who "My company has taken measures and it will continue to take the been, reasonably ascertainable using legitimate means (other that judicial or quasi-judicial proinformation is not publicly available.	e asserted any CBI claims in this ements truthfully and accurately a ich you have asserted. to protect the confidentiality of ese measures; the information is reby other persons (other than gover han discovery based on a showing occeding) without my company's corilable elsewhere; and disclosure of my company's competitive position	the information, not, and has not ment bodies) by of special need in asent; the	
	NĮA			
	NAME	SIGNATURE	DATE SIGNED	
	TITLE	TELEPHONE NO.		
[_]	Mark (X) this box if you attach	a continuation sheet.		

PART	B CORPORATE DATA
1.09	Facility Identification
CBI	Name [3]M]]A]C]&]S]]D]T]V][]S] []O]N]]]]]]]]]]]]
[_]	Address [3]2]]]]]][][][][][][][][][][][][][][][]
	[<u>S]p]r]i]n]g]f]i]e]]</u>]]]]]]]]]]]]]]]]]]]]]]]
	[M]0] [6]5]8]0]2][]]]]]
	Dun & Bradstreet Number $[0]4]-[3]9]3]-[7]8]9]5]$
	EPA ID Number
	Employer ID Number
	Primary Standard Industrial Classification (SIC) Code $\dots [2] \overline{8} \overline{9} \overline{9} \overline{1}$
	0ther SIC Code
	Other SIC Code[_]_]_]]
1.10	Company Headquarters Identification
CBI	Name [M]i]n]nessolt]a]]M]i]n]i]n]g]]&]]M]f]g]]]C]o
[_]	Address []]9]4]]E]als]t]]aln]d]]M]c[K]n]i]g]h]t]]R]d]
	[_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	[M]N [5]5]]4]4]-[]]0]0]0] State
	Dun & Bradstreet Number
	Employer ID Number
tJ	Mark (X) this box if you attach a continuation sheet.

1.11	Parent Company Identification
<u>CBI</u>	Name [M]i]n]n]e]s]o]t]a]]M]i]n]i]n]g]]&]]M]f]q].]]C]o] Address []T]9]4]]E]a]s]t]]a]n]d]]M]c]K]n]i]g]h]t]]R]d]
	[_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	Dun & Bradstreet Number
1.12	Technical Contact
CBI	Name []]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]
[_]	Title [M] a] n] a] g] e r]]]]]]]]]]]]]]]]]]
	Address [3]M]] C]e]n]t]e]r]] 2]2]5]] 3]N]-]09]]]]]]]]]]]]]]]]
	[_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	Telephone Number
1.13	This reporting year is from $[\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \$
[_]	Mark (X) this box if you attach a continuation sheet.

1.14	Facility Acquired $$ If you purchased this facility during the reporting year, provide the following information about the seller: N/A
CBI	Name of Seller []]]]]]]]]]]]]]]]]]
[_]	Mailing Address [_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	[_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	[_]_] [_]_]_]_]_][_]]_]_]_] State
	Employer ID Number
	Date of Sale
	Contact Person [_]_]_]_]_]_]_]_]_]_]_]_]_]
	Telephone Number
1.15	Facility Sold If you sold this facility during the reporting year, provide the following information about the buyer: ${\sf N/A}$
CBI	Name of Buyer [_]_]_]_]_]_]_]_]_]_]]]]]]]
[_]	Mailing Address [_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	[_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	[_]_] [_]_]_]_][_]_]_] State
	Employer ID Number
	Date of Purchase
	Contact Person [_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	Telephone Number
[_] 1	Mark (X) this box if you attach a continuation sheet.

1.16	For each classification listed below, state the quantity of the liste was manufactured, imported, or processed at your facility during the	
CBI	Classification	Quantity (kg/yr)
[_]		``
	Manufactured	0
	Imported	0
	Processed (include quantity repackaged)	. 205,595
	Of that quantity manufactured or imported, report that quantity:	
	In storage at the beginning of the reporting year	
	For on-site use or processing	0
	For direct commercial distribution (including export)	0
	In storage at the end of the reporting year	·0
	Of that quantity processed, report that quantity:	
	In storage at the beginning of the reporting year	6,207
	Processed as a reactant (chemical producer)	205,595
	Processed as a formulation component (mixture producer)	0
	Processed as an article component (article producer)	0
	Repackaged (including export)	·0
	In storage at the end of the reporting year	2,895

 $[\ \]$ Mark (X) this box if you attach a continuation sheet.

or a chemi	component of a mixture. D	cance on which you are requestroyide the following information is variable, reposit formulations.)	mation for each	ı component
	Component Name	Supplier Name	Composition (specify	rage % on by Weight precision, 45% ± 0.5%)
			Total	100%

2.04	State the quantity of the listed substance that your facility manufa or processed during the 3 corporate fiscal years preceding the report descending order.		
CBI		1	
[_]	Year ending	. [<u>T]2</u>] [
	Quantity manufactured	0	k
	Quantity imported	0	k
	Quantity processed	145,117	k
	Year ending	· [<u>T]</u> _2] [8	8] 6] Year
	Quantity manufactured	0	kg
	Quantity imported	0	k
	Quantity processed	196,364	kg
	Year ending	. [<u>1]2</u>] [{ Mo.	<u>3</u>] <u>5</u>] Year
	Quantity manufactured	0	kg
	Quantity imported	0	kg
	Quantity processed	136,364	kg
2.05 CBI	Specify the manner in which you manufactured the listed substance. appropriate process types.	Circle all	
[_]	N / A		_
	Continuous process		
	Semicontinuous process		
	Batch process		3
	_		
[_]	Mark (X) this box if you attach a continuation sheet.		

2.06 CBI	Specify the manner in appropriate process ty		he listed substance.	Circle all		
[_]		Continuous process				
	•					
	Semicontinuous process					
	Batch process			(3		
2.07 CBI	State your facility's substance. (If you ar question.)					
[_]		N/A				
LJ	Manufacturing capacity	,		kg/yr		
	Processing capacity .	• • • • • • • • • • • • • • • • • • • •		kg/yr		
2.08 CBI	If you intend to incremanufactured, imported year, estimate the incovolume.	l, or processed at any	time after your curr	ent corporate fiscal		
[_]		Manufacturing Quantity (kg)	Importing Quantity (kg)	Processing Quantity (kg)		
	Amount of increase			N/A		
	Amount of decrease			N/A		
[_]	Mark (X) this box if y	ou attach a continuat	ion choot	:		
r 1	mark (x) this box if y	ou actach a continuat	ion sheet.			

2.09	listed substance substance durin	argest volume manufacturing or processing proces, specify the number of days you manufactured of the reporting year. Also specify the average stype was operated. (If only one or two opera	or processed number of h	the listed
[<u>_</u>]			Days/Year	Average Hours/Day
	Process Type #1	(The process type involving the largest quantity of the listed substance.)		
		Manufactured	N/A	N/A
		Processed	111	_24
	Process Type #2	(The process type involving the 2nd largest quantity of the listed substance.)		
		Manufactured	N/A	
		Processed	N/A	
	Process Type #3	(The process type involving the 3rd largest quantity of the listed substance.)		
	į.	Manufactured	N/A	· .
		Processed	N/A	
2.10 <u>CBI</u> []	substance that chemical. Maximum daily is	um daily inventory and average monthly inventors was stored on-site during the reporting year in nventory	the form of	
[_]	Mark (X) this b	ox if you attach a continuation sheet.		

Related Product Types List any byproducts, coproducts, or impurities present with the listed substance in concentrations greater than 0.1 percent as it is manufactured, imported, or processed. The source of byproducts, coproducts, or impurities means the source from which the byproducts, coproducts, or impurities are made or introduced into the product (e.g., carryover from raw material, reaction product, etc.).					
CAS No. Chemical Name This question is all UK.	Byproduct, Coproduct or Impurity	Concentration (%) (specify ± % precision)	Source of By- products, Co- products, or Impurities		
<pre>"Use the following codes to design B = Byproduct C = Coproduct I = Impurity</pre>	gnate byproduct, copro	oduct, or impurity	y:		
	the listed substance in concentr tured, imported, or processed. means the source from which the introduced into the product (e.g etc.). CAS No. Chemical Name This question is all UK. This question is all UK. Use the following codes to desi B = Byproduct C = Coproduct	the listed substance in concentrations greater than 0 tured, imported, or processed. The source of byproduct means the source from which the byproducts, coproduct introduced into the product (e.g., carryover from raw etc.). CAS No. Chemical Name Or Impurity	the listed substance in concentrations greater than 0.1 percent as it tured, imported, or processed. The source of byproducts, coproducts, means the source from which the byproducts, coproducts, or impurities introduced into the product (e.g., carryover from raw material, reactivetc.). CAS No. Chemical Name Suproduct (%) (specify ± or Impurity % precision)		

 $[\ \]$ Mark (X) this box if you attach a continuation sheet.

<u>CBI</u>	imported, or processed the quantity of listed total volume of listed quantity of listed sub- listed under column b. the instructions for for	substance you use f substance used duri stance used captivel , and the types of e	or e ng t y on nd-u	ach product type he reporting year -site as a percen sers for each pro	as a percentage of the . Also list the tage of the value
	a. Product Types ¹	b. % of Quantity Manufactured, Imported, or Processed	_	c. % of Quantity Used Captively On-Site	d. Type of End-Users ²
		100			<u>I</u>
	1 Use the following code A = Solvent B = Synthetic reactan C = 'Catalyst/Initiator Sensitizer D = Inhibitor/Stabilic Antioxidant E = Analytical reagen F = Chelator/Coagulan G = Cleanser/Detergen H = Lubricant/Friction agent I = Surfactant/Emulsi J = Flame retardant K = Coating/Binder/Add 2 Use the following code I = Industrial	t r/Accelerator/ zer/Scavenger/ t t/Sequestrant t/Degreaser n modifier/Antiwear fier hesive and additives	L = M = N = O = O = O = O = O = O = O = O = O	Moldable/Castable Plasticizer Dye/Pigment/Coloe Photographic/Repand additives Electrodeposition Fuel and fuel ad Explosive chemice Fragrance/Flavor Pollution controe Functional fluide Metal alloy and Rheological modion Contro (specify) of end-users:	als and additives chemicals l chemicals s and additives additives
	T = Industrial CM = Commercial			pecify)	

a. roduct Types ¹	b. % of Quantity Manufactured, Imported, or Processed 100	% of Quantity Used Captively On-Site	
	Manufactured, Imported, or Processed	Used Captivel	У
B	100	100	
		<u> </u>	

Sensitizer Inhibitor/Stabilize Intioxidant Inalytical reagent Chelator/Coagulant/ Cleanser/Detergent/ Lubricant/Friction Igent Surfactant/Emulsifi Clame retardant Coating/Binder/Adhe	Accelerator/ r/Scavenger/ Sequestrant Degreaser modifier/Antiwear er sive and additives	L = Moldable/Casta M = Plasticizer N = Dye/Pigment/Co O = Photographic/I and additives P = Electrodeposis Q = Fuel and fuel R = Explosive cher S = Fragrance/Flast T = Pollution const U = Functional flast V = Metal alloy and W = Rheological mod X = Other (specify	micals and additives vor chemicals trol chemicals uids and additives nd additives odifier
he following codes	to designate the	type of end-users:	
Industrial Commercial			***************************************
	ynthetic reactant atalyst/Initiator/sensitizer shibitor/Stabilizer shibitor/Stabilizer shibitor/Stabilizer shibitor/Coagulant/Chelator/Coagulant/Cleanser/Detergent/Cubricant/Friction sent surfactant/Emulsificating/Binder/Adhe she following codes Industrial Commercial	synthetic reactant catalyst/Initiator/Accelerator/ censitizer chhibitor/Stabilizer/Scavenger/ chtioxidant chelator/Coagulant/Sequestrant cleanser/Detergent/Degreaser cubricant/Friction modifier/Antiwear cgent curfactant/Emulsifier clame retardant coating/Binder/Adhesive and additives the following codes to designate the Industrial CS = Cons Commercial Commercia	synthetic reactant Satalyst/Initiator/Accelerator/ Sensitizer Ship in the interval of the inte

	b.	c. Average %	d. .
Product Type ¹	Final Product's Physical Form ²	Composition of Listed Substance in Final Product	Type of End-Users
This ques	tion <u>is</u> N/A.		
1,, , , , , , , , , , , , , , , , , , ,	ing codes to designate p		
A = Solvent B = Synthetic in C = Catalyst/In Sensitizer D = Inhibitor/S Antioxidant E = Analytical F = Chelator/Co G = Cleanser/Do H = Lubricant/In agent I = Surfactant/In J = Flame retain K = Coating/Bin 2 Use the following	reactant nitiator/Accelerator/ Stabilizer/Scavenger/ treagent pagulant/Sequestrant etergent/Degreaser Friction modifier/Antiwe /Emulsifier rdant nder/Adhesive and additi	L = Moldable/Castable M = Plasticizer N = Dye/Pigment/Color O = Photographic/Reprand additives P = Electrodeposition Q = Fuel and fuel add R = Explosive chemica S = Fragrance/Flavor ar T = Pollution control U = Functional fluids V = Metal alloy and a W = Rheological modifives X = Other (specify) he final product's physic	cant/Ink and add cographic chemic n/Plating chemic ditives als and additive chemicals chemicals s and additives additives
A = Gas B = Liquid C = Aqueous sol D = Paste E = Slurry F1 = Powder	$\begin{array}{ccc} & & \text{F3} & = & \text{G} \\ \text{lution} & & \text{F4} & = & \text{O} \\ & & \text{G} & = & \text{G} \end{array}$	rystalline solid ranules ther solid el ther (specify)	*************************************
	ing codes to designate t $CS = C$ $H = 0$	onsumer	

2.15 CBI		e all applicable modes of transportation used to deliver bulk shipments of ted substance to off-site customers.	he			
<u> </u>	N/A Truck					
`'		ar				
		e, Vessel				
	_	ine				
	_	:				
	Other	(specify)	6			
2.16 <u>CBI</u> []	or pr	omer Use Estimate the quantity of the listed substance used by your custom repared by your customers during the reporting year for use under each catego ad use listed (i-iv). This question is N/A.	ers ry			
·	Categ	cory of End Use				
	i.	<u>Industrial Products</u>				
		Chemical or mixture k	g/yr			
		Article k	cg/yr			
	ii.	· Commercial Products				
		Chemical or mixture k	cg/yr			
		Article k	g/yr			
	iii.	Consumer Products				
		Chemical or mixture k	cg/yr			
		Article k	g/yr			
	iv.	0ther				
			cg/yr			
			tg/yr			
			cg/yr			
			cg/yr			
		Olikhown customer uses	-81.JI			
[_]	Mark	(X) this box if you attach a continuation sheet.				

PART	A GENERAL DATA				
3.01 <u>CBI</u>	Specify the quantity purchased and the average price paid for the listed substance for each major source of supply listed. Product trades are treated as purchases. The average price is the market value of the product that was traded for the listed substance.				
[_]	Source of Supply	Quantity (kg)	Average Price (\$/kg)		
	The listed substance was manufactured on-site.	N/A			
	The listed substance was transferred from a different company site.	N/A			
	The listed substance was purchased directly from a manufacturer or importer.	201,577			
	The listed substance was purchased from a distributor or repackager.	N/A			
	The listed substance was purchased from a mixture producer.	N/A			
3.02 CBI	Circle all applicable modes of transportation used t your facility.	o deliver the lis	ted substance to		
[_]	Truck		(1		
	Railcar		2		
	Barge, Vessel				
	Pipeline		4		
	Plane		5		
	Other (specify)	• • • • • • • • • • • • • • • • • • • •	6		
[-]	Mark (X) this box if you attach a continuation sheet				

3.03 <u>CBI</u>	a.	Circle all applicable containers used to transport the listed subsfacility.	tance to	your
[_]		Bags	• • • • • • •	····· 1
		Boxes		2
		Free standing tank cylinders		3
		Tank rail cars		4
		Hopper cars		5
		Tank trucks		6
		Hopper trucks		7
		Drums		8
		Pipeline		9
		Other (specify)		10
	b.	If the listed substance is transported in pressurized tank cylinde cars, or tank trucks, state the pressure of the tanks.		
		Tank cylinders		mmHg
		Tank cylinders Tank rail cars		
		·		mmHg
		Tank rail cars		mmHg
		Tank rail cars		mmHg
		Tank rail cars		mmHg
		Tank rail cars		mmHg
		Tank rail cars		mmHg
		Tank rail cars		mmHg
		Tank rail cars		mmHg
		Tank rail cars		mmHg
		Tank rail cars		mmHg
		Tank rail cars		mmHg

3.04 CBI	of the mixture, the nam	e of its supplier(s) tion by weight of th ssed during the repo	form of a mixture, list the or manufacturer(s), an est listed substance in the morting year.	imate of the
	Trade Name	Supplier or Manufacturer	Average % Composition by Weight (specify ± % precision)	Amount Processed (kg/yr)
	•			

.05 <u>BI</u>	State the quantity of the listed substance used as a raw material during the reporting year in the form of a class I chemical, class II chemical, or polymer, and the percent composition, by weight, of the listed substance.			
_		Quantity Used (kg/yr)	% Composition by Weight of Listed Sub- stance in Raw Material (specify ± % precision	
	Class I chemical	205,595	98,5-100 % ± UK	
	Class II chemical			
	Polymer			
	,	 	And the state of t	

	SEC	rion 4 Physical/Chemic	CAL PROPERTIES		
Genera	al Instructions:			3	
If you 4 tha	u are reporting on a mix t are inappropriate to m	ture as defined in the ixtures by stating "NA	glossary, reply to e	questions in Section	
notice	uestions 4.06-4.15, if ye that addresses the inf mile in lieu of answerin	ormation requested, yo	u may submit a copy 🤄	abel, MSDS, or other or reasonable	
PART A	A PHYSICAL/CHEMICAL DAT	A SUMMARY			
4.01 <u>CBI</u>	Specify the percent pur substance as it is manu substance in the final import the substance, o	factured, imported, or product form for manuf	processed. Measure acturing activities,	the purity of the at the time you	
l J		Manufacture	Import	Process	
	Technical grade #1	% purity	% purity	> 98.5 % purity	
	Technical grade #2	% purity	% purity	% purity	
*	Technical grade #3	% purity	% purity	%_purity	
	¹ Major = Greatest quant	ity of listed substanc	e manufactured, impo	rted or processed.	
4.02	Submit your most recent substance, and for ever an MSDS that you develowersion. Indicate whet appropriate response.	y formulation containi ped and an MSDS develo	ng the listed substa ped by a different s	nce. If you possess ource, submit your	
	Yes			(1	
	No 2				
	Indicate whether the MSDS was developed by your company or by a different source.				
	Your company				
	Another source			2	



MATERIAL SAFETY DATA

OCEAN® Network
EMERGENCY PHONE 1-800-OLIN-911

SECTION I - IDENTIFICATION

MSDS FILE 563

CHEMICAL NAME & SYNONYMS Toluene Diisocyanate 80-20		
CHEMICAL FAMILY Isocyanate	FORMULA CgH6N2C2	PRODUCT TDI 80-20
DESCRIPTION Clear water white to pungent odor	o pale yellow liquid with sharp	CAS NO. 26471-62-5

SECTION II - NORMAL HANDLING PROCEDURES

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE

Harmful if swallowed. Avoid contact with eyes, skin or clothing. Upon contact with skin or eyes, wash off with water. Avoid breathing mist or vapor. Protect against physical damage. Store in a cool, dry, well-ventilated place, away from areas where a fine hazard may be acute. Outside or detached storage is preferred. Blanket storage tanks with inent gas (nitrogen) or dry air. Separate from oxidizing materials.

PROTECTIVE EQUIPMENT	VENTILATION REQUIREMENTS
EYES Goggles	As required to keep airporne concentrations below TLV
GLOVES Rubber, NBR or PVA	
OTHER Coveralls, impervious footwear	

SECTION III - HAZARDOUS INGREDIENTS

BASIC MATERIAL	OSHA PEL	LDSO	LC50	SIGNIFICANT EFFECTS
=Toluene-2.4-diisocyanate (80%)	0.02 pom	5.8 g/kg (rat)	10 ppm/4 hrs	Skin, eye. mucous memorane irritation.
CAS No.: 584,-84-9			(mouse)	Pulmonary irritant. Allergic sensitization
				to skin and respiratory tract. May cause asthma attacks.
*Toluene-2.6-diisocyanate(20%),CAS No.:91-08-7	None established	No data	11 ppm/4 hrs-mouse	Irritation

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT 270'F COC METHOD	OSHA CLASSIFICATION Not Regulated (Ignitable)	FLAMMABLE LOWER UPPER EXPLOSIVE 0.9% 9.5%	
containers cool	rbon dioxide or dry chemical. Use wat		
SPECIAL FIRE HAZARD & FIRE FI self-contained breathing appa	GHTING PROCEDURES use NIOSH/MSHA aportratus when any material is involved in	oved positive pressure in a fire.	

SECTION V - HEALTH HAZARD DATA

			IRE May car and respira								tomacr	a. skin	. Ailer	ngic
30.13				EMERGENCY										
SKIN	Immediately	/ flush	thoroughly	with water	for	15 r	rinutes	, са	ll a	phys	cian.			
EYES	Immediately	/ flusn	thoroughly	with water	for	15 (inutes	. са	li a	phys	ician.			
****	TION Immed	a+alv i	drink large	quantitie	s of w	ate	to di	ilute						

INHALATION Immediately remove victim to fresh air. Call a physician.

SECTION VI - TOXICOLOGY (PRODUCT)

ACUTE ORAL LD 50 5.8 g/kg (rats). Harmful if swallowed.

ACUTE DERMAL LD 50 > 2 g/kg (rappits) ACUTE INHALATION LC 50 10 ppm/4 hrs (mouse) CARCINOGENICITY Oral Exposure-Positive NTP Bioassay MUTAGENICITY Not known to be mutagenic EYE IRRITATION Irritation and/or burns PRIMARY SKIN IRRITATION

Irritation and/or burns

PRINCIPAL ROUTES OF ABSORPTION

Inhalation, dermal contact

EFFECTS OF ACUTE EXPOSURE May cause irritation to lungs, eyes, throat, stomach, skin. Allergic sensitization of skin and respiratory tract. Corneal injury may occur.

EFFECTS OF CHRONIC EXPOSURE Damage/allergic sensitization to lungs. Innalation studies indicate not carcinogenic. Carcinogenic risk from industrial use is not significant.

SECTION VII - SPILL AND LEAKAGE PROCEDURES (CONTROL PROCEDURES)

ACTION FOR MATERIAL RELEASE OR SPILL

Wear NIOSH/MSHA approved positive pressure supplied air respirator. Follow OSHA regulations for respirator use (see 29 CFR 1910.134), Wear goggles, coveralls and impervious gloves and boots. Add dry non-compustible absorbent, sweep up material and place in an approved DOT container. Add an equal amount of neutralizing solution to the container (90-95% water, 5-10% ammonia). Clean remaining surfaces with neutralizing solution and add this to container. Isolate container in a well-ventilated place and do not seal for 24 hrs. Ammonia vapors may be generated until solution is neutralized. Wash all contaminated clothing before reuse. In the event of a large spill use the telephone number shown on the front of this sheet.

TRANSPORTATION EMERGENCY, CONTACT CHEMTREC 800-424-9300

THE MIXTURE OR TRADE NAME PRODUCT HEREIN CONTAINS A TOXIC CHEMICAL(S) SUBJECT TO THE REPORTING REQUIREMENTS OF SECTION 313 OF TITLE III OF THE SUPERFUND AMENDMENTS AND REAUTHORIZATION ACT OF 1986 AND 40 CFR PART 372. THE SARA 313 CHEMICALS ARE LISTED IN SECTION III AND ARE INDICATED BY AN ASTERISK (*).

SECTION VIII - SHIPPING DATA

D.O.T. Toluene diisocyanate Poison B UN 2078

SECTION IX - REACTIVITY DATA

STABLE X UNSTABLE AT __C __ F HAZARDOUS MAY OCCUR Y POLYMERIZATION WILL NOT OCCUR

CONDITIONS TO AVOID

Water or incompatible materials in a closed system, excess heat INCOMPATIBILITY(MATERIAL TO AVOID)

Acids, bases and alcohols, surface active materials HAZARDOUS DECOMPOSITION PRODUCTS

Carbon monoxide, nitrogen oxides, hydrogen cyanide

SECTION X - PHYSICAL DATA

MELTING POINT 53-56"	I VAPOR PRESSURE . O 1 mmHg , 20 C	VOLATILES No data
BOILING POINT 484 F	SQLUBILITY IN WATER Insoluble	I EVAPORATION RATE No data
SPECIFIC GRAVITY(H20=1) 1.22	PH No data	VAPOR DENSITY(AIR=1)6.0
3. 40-11-1		

98957001


INFORMATION: FURNISHED TO

FURNISHED BY

DATE DECEMBER 5, 1968

ATTN: DEPT HANDLING MATE SAFETY DATA SHEETS WORUM CHEMICAL CO 2130 ENERGY PARK DR ST PAUL MN 55108

Department of Environmental Hygiene and Toxicology (203) 789-5436



120 Long Ridge Road, Stamford, Connecticut 06904 OCEAN® Network

EMERGENCY PHONE 1-800-OLIN-911

Submit a copy or reasonable facsimile of any hazard information (other than an MSDS) that is provided to your customers/users regarding the listed substance or any formulation containing the listed substance. Indicate whether this information has been submitted by circling the appropriate response.
Yes

4.04 For each activity that uses the listed substance, circle all the applicable number(s) corresponding to each physical state of the listed substance during the activity listed. Physical states for importing and processing activities are determined at the time you import or begin to process the listed substance. Physical states for manufacturing, storage, disposal and transport activities are determined using the final state of the product.

		sical State	l State		
Activity	Solid	Slurry	Liquid	Liquified Gas	Gas
Manufacture	1	2	3	4	5
Import	1	2	3	4	5
Process	1	2	3	4	5
Store	1	2	3	4	5
Dispose	1	2	3	4	5
Transport	1	2	3	4	5

^[] Mark (X) this box if you attach a continuation sheet.

particle importing I listed s _ storage,	age distribution of t es ≥10 microns in dia ng and processing act substance. Measure t , disposal and transp	meter. Measur ivities at the he physical st	e the ph time yo ate and	ysical st u import particle	ate and or begi sizes f	particle n to proc or manufa	e sizes fo ess the ecturing
_]	Not App	olicable.		• .			
Physical State	<u>.</u>	Manufacture	Import	Process	Store	Dispose	Transpor
Dust	<1 micron						
	1 to <5 microns						
	5 to <10 microns						
Powder	<1 micron						
	1 to <5 microns						
	5 to <10 microns						
Fiber	<1 micron						
	1 to <5 microns						
	5 to <10 microns	-					
Aerosol	<1 micron			-			
	1 to <5 microns						
	5 to <10 microns						

		SECTION 5 ENVIRONMENTA	L FATE		
PART	A R	ATE CONSTANTS AND TRANSFORMATION PRODUCTS			
5.01	Ind	icate the rate constants for the following tr	ansformation proce	sses.	•
	a.	Photolysis:			
		Absorption spectrum coefficient (peak)	871 (1/M cm)	at 284	nm
		Reaction quantum yield, 6		at	
		Direct photolysis rate constant, k _p , at	1.2×10^{-3} 1/hr	when NO ₂ photo	olysis rat
	ъ.	Oxidation constants at 25°C:		is 0.37/hr ⁽²⁾	
		For 10_2 (singlet oxygen), k_{ox}	UK		1/M hr
		For RO ₂ (peroxy radical), k _{ox}			1/M hr
	c.	Five-day biochemical oxygen demand, BOD ₅		reaction	mg/l
	d.	Biotransformation rate constant:			
		For bacterial transformation in water, k_b	No oxygen consumed	(2)	1/hr
		Specify culture	in modified MITI test	(3)	-
	e.	Hydrolysis rate constants:			`
		For base-promoted process, k _B	UK		1/M hr
		For acid-promoted process, k _A	UK		1/M hr
		For neutral process, k _N			1/hr
	f.	Chemical reduction rate (specify conditions			_
	g.	Other (such as spontaneous degradation) conditions.	Polyurea formation un	der hydrolytic	-

[_]	Mark	(X)	this	box	if	you	attach	a	continuation	sheet.

PART	в Р	ARTITION COEFFICIENT	S	. Anglandig	•		
5.02	a.	Specify the half-li	fe of the l	isted substan	nce in the followin	ng media.	
		<u>Media</u>			Half-life (specif	fy units)	·
		Groundwater		دد 1'day in	water solution (4)		
		Atmosphere		26 hr (2			
		Surface water		<< 1 day in	water solution (4)		
		Soil	i	<pre>< 1 day (4</pre>	.)		-
	ъ.	Identify the listed life greater than 2	substance' 4 hours.	s known trans	sformation products	s that have	a half-
		CAS No.		Name	Half-life (specify units)	<u> M</u> e	edia
		Not found	Polyurea		> 1 yr	in <u>water an</u>	
		95-80-7	2,4-Toluene	e diamine	< 1 day(in <u>treatme</u> n	al waste-wate <u>t plant (4)</u>
		823-40-5	2,6-Toluene	e diamine	<pre></pre>) in	
		5206-52-0	<u>Urea, N, N</u> 4-methylpho	- bis (3-isocyan enyl)		in (5,6)	
5.03		ecify the octanol-wat					_ at 25°C
5.04	Spe	ecify the soil-water	partition o	coefficient,	K _a reacts wi	ith water	at 25°C
	Soi	l type		• • • • • • • • • • • • • • • • • • • •			_
5.05	Spe	ecify the organic carefficient, K _{oc}	bon-water p	partition	2.60 = 10	og	_ at 25°C
5.06	Spe	ecify the Henry's Law	Constant,	Н		.88 at	m-m³/mole
[_]	Mar	ck (X) this box if yo	ou attach a	continuation	sheet.		


		<u>Test¹</u>
None detected	Moina macrocopa Straus	Not defined (4)
None detected	Cyprinus carpio	Not defined (4)
		<u> </u>
¹ Use the following cod	es to designate the type of tes	t:
F = Flowthrough S = Static		
(1) Phillips and Nachod,	eds., Organic Electronic Spectral Data	, Vol. IV, pg. 200.
(2) K. H. Becker, V. Bast methylenedianiline un A: Chemistry, <u>45</u> (19	ian and Th. Klein, The reactions of to der simulated atmospheric conditions, 88) 195-205.	luenediisocyanate, toluenediami J. Photochem. and Photobiol.,
Report to the Interna	rger, R. Kanne and Waklebert, Ecotoxici tional Isocyanate Institute, E-CE-41, n Air, Soil and Water, Polyurethanes W I/FSK.	1986. Quoted in D. S. Gilbert.
(4) F. K. Brochhagen and Cellular Polymers, 3	B. M. Grieveson, Environmental aspects (1984) 11-17.	of isocyanates in water and so
(5) K. Marcali, Microdete 552-558.	rmination of toluenediisocyanate in at	mosphere, Anal. Chem. <u>29</u> (1957)
(6) G. A. Campbell, T. J. 3,906,019 (1975), Che	Dearlove and W. C. Meluch, Di (isocya m. Abs. 84:5655h.	natotolyl) urea, U.S. Patent

[_]	the listed substance sold or transfer		
ι,	Market	Quantity Sold or Transferred (kg/yr)	Total Sales Value (\$/yr)
	Retail sales		
	Distribution Wholesalers		
	Distribution Retailers		
	Intra-company transfer		
	Repackagers		
	Mixture producers		
	Article producers		
	Other chemical manufacturers or processors		
	Exporters		
	Other (specify)		
6.05 <u>CBI</u>	Substitutes List all known commerce for the listed substance and state the feasible substitute is one which is earlier in your current operation, and which performance in its end uses.	ne cost of each substitut economically and technolo	e. A commercially gically feasible to use
[_]	Substitute		Cost (\$/kg)
	None known.		

	SECTION 7 MANUFACTURING AND PROCESSING INFORMATION
For qu	al Instructions: uestions 7.04-7.06, provide a separate response for each process block flow diagram ded in questions 7.01, 7.02, and 7.03. Identify the process type from which the mation is extracted.
PART	A MANUFACTURING AND PROCESSING PROCESS TYPE DESCRIPTION
7.01 CBI	In accordance with the instructions, provide a process block flow diagram showing the major (greatest volume) process type involving the listed substance.
[_]	Process type Urethone

[Mark (X) this box if you attach a continuation sheet.

URETHANE PROCESSING DIAGRAM




7.03	In accordance with the instructions, provide a process block flow diagram showing all process emission streams and emission points that contain the listed substance and which, if combined, would total at least 90 percent of all facility emissions if not treated before emission into the environment. If all such emissions are released from one process type, provide a process block flow diagram using the instructions for question 7.01. If all such emissions are released from more than one process type, provide a process block flow diagram showing each process type as a separate block.					
CBI	B Inethane	N.				
11	Process type Urethane					
	 Vented emissions Fugitive emissions from lines to mixer 	SARA Section 313 65 lbs 32 lbs				
		•				
	•					
			•			

 $[\overline{X}]$ Mark (X) this box if you attach a continuation sheet.

.703

URETHANE PROCESSING DIAGRAM



Process type Urethane Processing							
Unit Operation ID Number	Typical Equipment Type	Operating Temperature Range (° K)f	Operating Pressure Range (mm Hg)	Vesse Composi			
7.1	Weigh tank	70-95 °F	Vented 760 mm Hg	Stee1			
7.2	Reactor	70-180 °F	760 mm Hg Vented	Stainless			
7.3	Storage tank	45-70 °E.	_760_mm_Hg	Steel			
7.4	Mixer 1	70-150 °F	<u>Vented/Vacu</u> um	<u>Stainless</u>			
7.5	B1ender	70-300 °F	Vented	Steel			
7.6	Mixer 2	70-120 °F	<u>Vented</u>	Stainless			
							
							

7.05	process block f	process stream identified in your flow diagram is provided for monopolete it separately for each	ore than one process typ	liagram(s). If a be, photocopy thi
<u>CBI</u>				
[_]	Process type	Urethane Processing		
	Process Stream ID Code	Process Stream Description	Physical State ¹	Stream Flow (kg/yr)
	7A	TDI	OL	205,595
	7B	Catalyst	OL	1,439
		Solvent	OL	205,595
		Polyol	<u>OL</u>	205,595
		Urethane Prepolymer	<u>OL</u>	2,055,950
	7 F	Filler	SO	1,654,212

OL.

OL/SO

425_369

1,240,659

GC = Gas (condensible at ambient temperature and pressure)

Pigment/Catalyst/Solvent

Resins

- GU = Gas (uncondensible at ambient temperature and pressure)
- SO = Solid

7G

7H

- SY = Sludge or slurry
- AL = Aqueous liquid
- OL = Organic liquid
- IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene)

¹Use the following codes to designate the physical state for each process stream:

 $^{[\}overline{X}]$ Mark (X) this box if you attach a continuation sheet.

<u>.</u> 1	Process type	Urethane		
•	Process Stream ID Code	Process Stream Description	Physical State ¹	Stream Flow (kg/y
	<u>7</u> I	Solvent	OL	531,711
	7 J	Resin Solution	OL	1,772,370
	7K	Scrap solvent clean out	<u>OL</u>	20,559 *
	7L	Scrap solvent clean out	OL	59,079 *
	7M	Product	OL	5,907,902
	Z 0,P,Q	Vent to atmosphere	GU	17,000
	GC = Gas (cond GU = Gas (unco SO = Solid SY = Sludge or AL = Aqueous l OL = Organic l IL = Immiscibl	iquid	nd pressure) and pressure)	

[_]		e <u>Urethane</u>		_	W W 4 2 2 4
	Process Stream ID Code	b. Known Compounds ¹	c. Concen- 外 trations ^{2,3} (% or ppm)	d. Other Expected Compounds	e. Estimated Concentrations (% or ppm)
-	<u>7A</u>	IDI	100%	UK	N/A
	<u>7</u> B	Catalyst		UK	N/A
	<u>7C</u>	Solvent		UK	N/A
.06	continued be	elow			
		*All concentr	rations reporte	d as (EXW)	

_]	Process type	e Urethane			
	а.	b.	c.	d.	e.
	Process Stream ID Code	Known Compounds	Concen- trations ^{2,3} (% or ppm)	Other Expected Compounds	Estimated Concentrations (% or ppm)
	7D	Polyol	100%	none	N/A
	7E	Urethane	95%	UK	N/A
		IDT	5%	UK	N/A
	<u>7</u> F	Pigment	1.5%	none	N/A
	•	Catalyst	5.5%	none	N/A
		_ Solvent	93%	none	N/A
.06	continued b	elow			

a. rocess Stream D Code	b. Known Compounds Fillers	C. Concen- trations ^{2,3} (% or ppm)	d. Other Expected	e. Estimated
rocess Stream D Code	Known Compounds ¹	Concen- trations ^{2,3}	Other	
Stream O Code		trations ^{2,3}		Estimated
7G	Fillers		Compounds	Concentrations (% or ppm)
		100%	none	N/A
 7н	Resin	100%	none	N/A
. —				
7I <u> </u>	Solvent	100%	none	N/A
•				
<u></u>				
ntinued belo	w			
	71		7I Solvent 100%	7I Solvent 100% none

a.	b.	c.	d.	e.
Process Stream ID Code	Known Compounds	Concen- trations ^{2,3} (% or ppm)	Other Expected Compounds	Estimated Concentration (% or ppm)
7 J	Resin	70%	none	N/A
	Solvent	30%	none	N/A
7 K	Scrap prepolymer	4-5% (E)(W)	polyols	UK
	Toluene	95% (E)(W)	TDI	∢ 0.05% (E)(W)
7L	Scrap product	4-5% (E)(W)	TDI	~ 0.05% (E)(W)
	Toluene	95% (E)(W)		
	The second secon			


	a.	b.	c.	d.	é•
	Process Stream ID Code	Known Compounds ¹	Concen- trations ² , ³ (% or ppm)	Other Expected Compounds	Estimated Concentrations (% or ppm)
	7M	Product	100% (E)(W)	none	N/A
	70	Nitrogen	100% (E)(W)	TDI	UK - (trace)
	7 P,Q	Toluene	< 1% (E)(W)	TDI	UK - (trace)
		Nitrogen	> 99% (E)(W)		
	•				^
 7.06	continued b				

PART A RESIDUAL TREATMENT PROCESS DESCRIPTION

8.01 In accordance with the instructions, provide a residual treatment block flow diagram which describes the treatment process used for residuals identified in question 7.01.

CBI

Process type Urethane



[] Mark (X) this box if you attach a continuation sheet.

8.05 CBI	diagram process	n(s). If a r type, photo	esidual trea copy this qu	tment block f estion and co	in your residu low diagram is mplete it sepa r explanation	provided for rately for ea	more than one ch process
[_]	Process	type	Urethane	e Processing		-	
	a.	b.	c.	d.	е.	f.	g.
	Stream ID Code	Type of Hazardous Waste	Physical State of Residual ²	Known Compounds ³	Concentra- tions (% or ppm) ^{4,5,6}	Other Expected Compounds	Estimated Concen- trations (% or ppm)
	8 A	I	OL	Product	4-5% (E)(W)	TDI	0.05% (E)(W)
				Toluene	95% (E)(W)		·
				,			
							_
							_
							-

8.05	continu	ed below					

8.05 (continued) ¹Use the following codes to designate the type of hazardous waste: I = Ignitable C = Corrosive R = Reactive E = EP toxicT = ToxicH = Acutely hazardous ²Use the following codes to designate the physical state of the residual: GC = Gas (condensible at ambient temperature and pressure) GU = Gas (uncondensible at ambient temperature and pressure) S0 = SolidSY = Sludge or slurry AL = Aqueous liquid OL = Organic liquid IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene) 8.05 continued below

8.05	(continued)		•. •. • • • • • • • • • • • • • • • • •
	that are present i Assign an additive column d. (Refer	package introduced into a process n each additive package, and the package number to each additive to the instructions for further ex ary for the definition of additive	concentration of each component package and list this number in xplanation and an example.
	Additive Package Number	Components of Additive Package	Concentrations(% or ppm)
	1	This question is N/A.	
	2		
	3		
			· · · · · · · · · · · · · · · · · · ·
	4		
	5		
	⁴ Use the following c	odes to designate how the concent	ration was determined:
	A = Analytical resu E = Engineering jud	gement/calculation	
8.05	continued below	·	
<u></u>	Mark (X) this box if	you attach a continuation sheet.	

helow.	the analytical test methods used and their detection limi	is in the tai
bclo**	Assign a code to each test method used and list those cod	es in column
Code	<u>Method</u>	Detection (± ug.
1	This question is N/A.	
2		
_3		
4		
_5		
6		

[_] Mark (X) this box if you attach a continuation sheet.

Process	type	<u>Urethar</u>	e Processing			
a.	b.	c.	d.	e.	f. Costs for	g.
Stream ID Code	Waste Description Code	Management Method Code ²	Residual Quantities (kg/yr)	Management of Residual (On-Site Off-S	0ff-Site (%) Management	Changes Management Methods
8 A	B 70	3I	79,640	100%	\$ 0.51	none
	solvent/produc clean out	t		<u> </u>		
						4
					· · · · · · · · · · · · · · · · · · ·	
	•					
					<u> </u>	
	-			_	aste description	

[_]		Ch	oustion amber ture (°C)	Temp	tion of erature nitor	In Co	ence Time mbustion (seconds)
	Incinerator	Primary	Secondary	Primary	Secondary	Primary	Secondary
	1						
	2						
	3					<u> </u>	
			of Solid Wast propriate resp		s been submit	tted in lieu	of response
	Yes	• • • • • • • • • • • • • • • • • • • •					1
	No	• • • • • • • • • •				• • • • • • • • • • • • • • • • • • • •	2
8.23 CBI	Complete the fare used on-si	te to burn k flow diag	the residuals	three larges s identified	t (by capacit in your proc	ess block o	r residual
	are used on-si treatment bloc Not Applica Incinerator 1 2 3	te to burn k flow diag ble.	the residuals ram(s). Air Po Control	ollution Device	in your proc	Type: Emission Avai	r residual s of ns Data lable
CBI	Are used on-sitreatment block Not Application Incinerator 2 3 Indicate by circle	te to burn k flow diag ble. if Office ing the app	of Solid Wast	ollution l Device te survey ha	in your prod	Type: Emission Avai	r residual s of ns Data lable of response
CBI	Are used on-sitreatment block Not Application Incinerator 1 2 3 Indicate by circle Yes	te to burn k flow diag ble. if Office ing the app	of Solid Wast	ollution l Device te survey habonse.	s been submit	Type: Emission Avai	of response
CBI	Are used on-sitreatment block Not Applica Incinerator 1 2 3 Indicate by circl Yes	te to burn k flow diag ble. if Office ing the app	of Solid Wast	ollution l Device te survey ha	s been submit	Type: Emission Avai	of response

PART A EMPLOYMENT AND POTENTIAL EXPOSURE PROFILE

9.01 Mark (X) the appropriate column to indicate whether your company maintains records on the following data elements for hourly and salaried workers. Specify for each data element the year in which you began maintaining records and the number of years the records for that data element are maintained. (Refer to the instructions for further explanation and an example.)

-	Data are Mai	intained for Salaried	: Year in Which Data Collection	Number of Years Records
Data Element	Vorkers	Workers	Began	Are Maintained
Date of hire	<u> </u>	X	1975	indefinitely
Age at hire	<u> </u>	X	1975	indefinitely
Work history of individual before employment at your				
facility	NA	<u>NA</u>	NA	NA
Sex	<u> </u>	X	1975	indefinitely
Race	X	X	1975	indefinitely
Job titles	<u> </u>	<u> </u>	1975	indefinitely
Start date for each job title	<u> </u>	X	1975	indefinitely
End date for each job title	X	X	1975	indefinitely
Work area industrial hygiene monitoring data		NA	NA ·	NA
Personal employee monitoring data	NA_	NA	NA	NA
Employee medical history	<u> </u>	X	about 1960	<u>indefinitely</u>
Employee smoking history	<u>NA</u>	NA	NA	NA
Accident history	X	X	about 1960	<u> Indefinitely</u>
Retirement date	. <u> </u>	<u> </u>	1932	<u>indefinitely</u>
Termination date	X	<u> </u>	1932	indefinitely
Vital status of retirees	X	<u> </u>	1932	indefinitely
Cause of death data	<u> </u>	X	_about 1960	<u>indefinitely</u>

	Mark	(X)	this	box	if	you	attach	a	continuation	sheet.
--	------	------------	------	-----	----	-----	--------	---	--------------	--------

^{* 3}M does I.H. monitering of work areas, but data is not maintained in worker files. See Question 9.08.

In accordance with the instructions, complete the following table for each activity in which you engage. <u>CBI</u> d. b. c. e. a. Total Yearly Total Worker-Hours Workers Activity **Process Category** Quantity (kg) N/A N/A N/A **Enclosed** Manufacture of the listed substance Controlled Release N/A N/A N/A N/A N/A N/A 0pen 9 205,564 7,992 **Enclosed** On-site use as reactant 31 N/A N/A Controlled Release (Vented) 0 N/A N/A 0pen N/A N/A N/A **Enclosed** On-site use as nonreactant N/A N/A N/A Controlled Release N/A N/A N/A 0pen N/A N/A **Enclosed** On-site preparation N/A of products Controlled Release N/A N/A N/A N/A N/A

N/A


0pen

^[] Mark (X) this box if you attach a continuation sheet.

listed substance.	s who may potentially come in contact with or be exposed to the
[]	
Labor Category	Descriptive Job Title
A	Resource Urethane Operator #8 (9)
В	Material Receivers (2)
C	
D	
E	
F	
G	
H	
I	
J	
J	
	-

9.04	In accordance with the instructions, provide your process block flow diagram(s) and indicate associated work areas.
<u>CBI</u>	Process type Urethane
	1 = Dump Port - Room 5 - Building 3
	2 = 2nd Floor - Mezzanine - Room 5 - Building 3

URETHANE PROCESSING DIAGRAM



BI] Process type	, Urethane
	OT CONTROL
Work Area ID	Description of Work Areas and Worker Activities
1	Resource Urethane Operator #8
2	
3 Te	
4	Material Receivers
5	Plant Emergency Squad Members
6	
7	
8	
9	
10	
Work Areas 1-3 = Workers dump poi	prepare batches per process standard. System is completely enclosed except for t, but material is re-acted at this point.
Work Area 4 = Materia respirat	Receivers transfer TDI from tank truck to storage tank. Positive air tion and protective clothing is worn.
Work Area 5 = Plant Er air resp	mergency Squad would be called out on a spill. Procedure specific, positive piration with protective clothing.

_]	Process type Urethane								
	Work area			· · · · · · · · · · · · · · · · · · ·	·				
	Labor <u>Category</u>	Number of Workers Exposed	Mode of Exposure (e.g., direct skin contact)	Physical State of Listed Substance	Average Length of Exposure Per Day ²	Number of Days per Year Exposed			
	A	2	Inhalation	GU	6 hrs	<u>~ 125</u>			
	B	2	Inhalation	GU	6 hrs	12			
	A	2	Inhalation	GU	3 hrs	<u>~125</u>			

	-								
	System is tot	ally sealed. Ex	posure would be to trace	e quantities only.					
		llowing codes of exposure:	to designate the p	hysical state of	the listed su	ibstance at			
		(condensible a		SY = Sludge or si					
	GU = Gas	erature and produced the condensible of the condens	at ambient	AL = Aqueous liqu OL = Organic liqu	uid				
		erature and pr udes fumes, va d	•	IL = Immiscible i (specify pha 90% water, i					
	² Use the fo	llowing codes	to designate avera	ge length of expe	osure per day:				
	B = Greate	utes or less r than 15 minu ing 1 hour	tes, but not	<pre>D = Greater than 2 hours, but not exceeding 4 hours E = Greater than 4 hours, but not</pre>					
	encecu.	ing i mour	r, but not	exceeding 8 l					

9.07	For each labor category represented in question 9.06, indicate the 8-hour Time Weighted Average (TWA) exposure levels and the 15-minute peak exposure levels. Photocopy this question and complete it separately for each process type and work area.					
CBI						
[_]	Process type	Urethane				
	Work area					
	Labor Category	8-hour TWA Exposure Level (ppm, mg/m³, other-specify)	15-Minute Peak Exposure Level (ppm, mg/m³, other-specify)			
	Work areas 1-5	0	0			
	North director i o					

	-					

0.08 CBI	If you monitor worke	er exposur	e to the li	sted substa	nce, compi	ete the to	illowing table
[_]	Sample/Test	Work Area ID	Testing Frequency (per year)	'Number of Samples (per test)	Who Samples	Analyzed In-House (Y/N)	Number of Years Record Maintained
	Personal breathing zone	1-3	1	2	Α	N	Indefinite
	General work area (air)	1-3	continuous	N/A	D	Υ	None
	Wipe samples						
	Adhesive patches						
	Blood samples						
	Urine samples						
	Respiratory samples						
	Allergy tests		-				
	Other (specify)						
	Other (specify)		-			<u></u>	
	Other (specify)						
	¹ Use the following of A = Plant industrianal B = Insurance carrows C = OSHA consultanal D = Other (specify	al hygien: ier t	ist	o takes the	monitorin	g samples:	

<u> </u>	analytical methodology used for each type of sample. Sample Type Sampling and Analytical Methodology								
۱,	Impingers with Marcali Solution Colorimetric								
			· · · · · · · · · · · · · · · · · · ·	·					
			si- manitaring for	the listed s	uhstance				
9.10	If you conduct person specify the following	al and/or amblent g information for e	ach equipment type	used.	doscunccy				
CBI				Avereging					
[_]	Equipment Type ¹	Detection Limit ²	Manufacturer	Averaging Time (hr)	Model Number				
	E	.001 A	MDA Scientific Inc.	Continuous	#7100				
			TEN SCIENCIFIC TIES	CONTOTTICOGO					
	¹ Use the following co	odes to designate p	ersonal air monitor	ing equipmen	it types:				
	A = Passive dosimete B = Detector tube	er							
	C = Charcoal filtra	tion tube with pump)						
	D = Other (specify)								
	Use the following codes to designate ambient air monitoring equipment types:								
	<pre>E = Stationary monitors located within work area F = Stationary monitors located within facility</pre>								
	G = Stationary monitors located at plant boundary H = Mobile monitoring equipment (specify)								
	I = Other (specify)								
	² Use the following codes to designate detection limit units:								
	A = ppm B = Fibers/cubic cer	ntimeter (f/cc)							
	C = Micrograms/cubi								

<u>CBI</u> [<u> </u>	Test Description	Frequency (weekly, monthly, yearly, etc.)
· <i>'</i>	Clinicals by doctor	yearly
	-	
	-	

12 <u>r</u>	Describe the engineering control to the listed substance. Phoprocess type and work area.	rols that you tocopy this q	use to reduce or e uestion and complet	eliminate wor e it separat	ker exposumely for each
-]	Process type	Urethane			
_	Work area			1-3	
	Engineering Controls	Used (Y/N)	Year Installed	Upgraded (Y/N)	Year Upgrade
	Ventilation:				
	Local exhaust	Υ	1980	N	N/A
	General dilution				
	Other (specify)				
	Vessel emission controls				
	Mechanical loading or packaging equipment				
	Other (specify)				
	-				
					·

	ork area Urethane				
	ent or Process Mo		· 	Reduction i Exposure Per	
None				N/A	
			-		
· w					
		·			
	-				
		·			

9.14	in each work area : substance. Photoco	nal protective and safety equi in order to reduce or eliminate opy this question and complete	e their exposure to the	e listed
CBI	and work area.		•	
[_]	Process type	Urethane		
	Work area		<u>1-5</u>	
			Wear or Use	
		Equipment Types	<u>(Y/N)</u>	
		Respirators	<u> </u>	
		Safety goggles/glasses	<u> </u>	
		Face shields		
		Coveralls	N	
		Bib aprons	N	
		Chemical-resistant gloves	Υ	
		Other (specify)		
		Tyvek Suits	<u> </u>	
		Chemical Resistant Boots	Υ	
	·			

<u>I</u> _] :	Process	type Urethan	e			
	Work Area	Respirator Type	Average Usage	Fit Tested (Y/N)	Type of Fit Test ²	Frequency of Fit Tests (per year)
	1-3	Positive air	E	N	N/A	N/A
	4	Positive air	E	N	N/A	N/A
,	5	Positive air	<u>E</u>	<u>N</u>	N/A	N/A
	A = Dai B = Wee C = Mon D = Onc E = Oth	ekly othly ce a year ner (specify) As requ	ired			
	A = Dai B = Wee C = Mon D = Onc E = Oth	ily ekly othly ce a year ner (specify) As reques e following codes to des	ired			
	A = Dai B = Wee C = Mon D = Onc E = Oth ² Use the	ily ekly othly ce a year eer (specify) As reque e following codes to des	ired	of fit tes		rs.
	A = Dai B = Wee C = Mon D = Onc E = Oth ² Use the	ily ekly othly ce a year ner (specify) e following codes to des	ired ignate the type	of fit tes		rs.
	A = Dai B = Wee C = Mon D = Onc E = Oth ² Use the	ily ekly othly ce a year ner (specify) e following codes to des	ired ignate the type	of fit tes		rs.
	A = Dai B = Wee C = Mon D = Onc E = Oth ² Use the	ily ekly othly ce a year ner (specify) e following codes to des	ired ignate the type	of fit tes		rs.
	A = Dai B = Wee C = Mon D = Onc E = Oth ² Use the	ily ekly othly ce a year ner (specify) e following codes to des	ired ignate the type	of fit tes		rs.
	A = Dai B = Wee C = Mon D = Onc E = Oth ² Use the	ily ekly othly ce a year ner (specify) e following codes to des	ired ignate the type	of fit tes		rs.

e all of the work p te worker exposure zed workers, mark a ing practices, prov n and complete it s type Ure	to the listed sub areas with warning vide worker trains separately for each	bstance (e.g., g signs, insuring programs, ch process typ	restrict en e worker dete etc.). Phote	trance only to ection and ocopy this
	thane .			
ea				
	• • • • • • • • • • • • • • • • • • • •		. 1,2,4 and	5
f closed system till rea	action has occurred	2 Continuous r	unning monitor	in area
en operating procedures	and process standard	is		
ive air respirators and	neutralizer in immed	liate area 5 L	lse of intermedi	ate weigh tank
al valving and venting	7 Regular maintena	ance Pm's on equip	ment and monito	r
compartment ventilation				
e (X) how often you or spills of the list ely for each process type Uret	sted substance. ss type and work thane	Photocopy this area.	k used to cl question an	ean up routine d complete it
eping Tasks	Less Than Once Per Day	1-2 Times Per Day	3-4 Times Per Day	More Than 4 Times Per Day
ıg		As Required		
ing	NA	NA	NA	N
flushing of floors		As Required		
(specify)				
n	g ushing of floors	g M ushing of floors	g NA NA ushing of floors As Required pecify)	g NA NA NA NA Ushing of floors As Required

19 31	Describe all of the work preliminate worker exposure to authorized workers, mark armonitoring practices, proviquestion and complete it seems.	eas with warning de worker traini	stance (e.g., signs, insul ng programs.	ce worker dete etc.). Photo	ection and ocopy this
_ _]	Process type Mate				
	Work area			3	
	1 Material Receivers use chemic transfer from truck to tank	al resistant suits ((Tyvek) and posit	cive air respirat	ors when making
	Cranster Troll Cruck to tank				
	2 Signs are put up to warn othe	r people that a TDI	transfer is occi	urring and to sta	y out of the area
	3 Neutralizer is in area				
20	Indicate (X) how often you leaks or spills of the lis separately for each proces	ted substance. s type and work	rnotocopy thi	sk used to cl s question an	ean up routine d complete it
20	leaks or spills of the lis	ted substance. s type and work rial Receivers	area.	sk used to cl s question an	ean up routine d complete it
20	leaks or spills of the lis separately for each proces Process type Mate	ted substance. s type and work rial Receivers	area.	sk used to cl s question an 3 3-4 Times Per Day	More Than 4
20	leaks or spills of the lis separately for each process Process type Mate Work area	ted substance. s type and work rial Receivers	rnotocopy thi area 1-2 Times	3 3-4 Times	More Than 4
20	leaks or spills of the lis separately for each process. Process type Mate Work area	ted substance. s type and work rial Receivers	rnotocopy thi area 1-2 Times	3 3-4 Times	More Than 4
20	leaks or spills of the lis separately for each proces Process type Mate Work area Housekeeping Tasks Sweeping	ted substance. s type and work rial Receivers Less Than Once Per Day	1-2 Times Per Day	3 3-4 Times Per Day	More Than 4
20	leaks or spills of the lis separately for each proces Process type Mate Work area Housekeeping Tasks Sweeping Vacuuming	ted substance. s type and work rial Receivers Less Than Once Per Day	1-2 Times Per Day	3 3-4 Times Per Day	More Than 4 Times Per Da
20	leaks or spills of the lis separately for each process Process type Mate Work area Housekeeping Tasks Sweeping Vacuuming Vacuuming Vater flushing of floors	ted substance. s type and work rial Receivers Less Than Once Per Day	1-2 Times Per Day	3 3-4 Times Per Day	More Than 4
20	leaks or spills of the lis separately for each process Process type Mate Work area Housekeeping Tasks Sweeping Vacuuming Vacuuming Vater flushing of floors	Less Than Once Per Day NA	1-2 Times Per Day	3 3-4 Times Per Day	More Than 4 Times Per Da
20	leaks or spills of the lis separately for each process Process type Mate Work area Housekeeping Tasks Sweeping Vacuuming Vacuuming Vater flushing of floors	Less Than Once Per Day NA	1-2 Times Per Day	3 3-4 Times Per Day	More Than 4 Times Per Da

9.21	Do you have a written medical action plan for responding to routine or emergency exposure to the listed substance?
	Routine exposure
	Yes
	No 2
-	Emergency exposure
	Yes 1
	No 2
	If yes, where are copies of the plan maintained?
	Routine exposure:
	Emergency exposure:
9.22	Do you have a written leak and spill cleanup plan that addresses the listed substance? Circle the appropriate response.
	Yes
	No 2
	Manual 10 To war where are copies of the plan maintained? Supervisors Area Section 10.10 1.
	If yes, where are copies of the plan maintained? Supervisors Area Section 10.10 1. SPCC & RCRA plans Has this plan been coordinated with state or local government response organizations?
	Circle the appropriate response.
	Yes
	No 2
9.23	Who is responsible for monitoring worker safety at your facility? Circle the appropriate response.
	Plant safety specialist 1
	Insurance carrier 2
	OSHA consultant 3
	Other (specify) 4
<u> </u>	Mark (X) this box if you attach a continuation sheet.

SECTION 10 ENVIRONMENTAL RELEASE

General Instructions:

Complete Part E (questions 10.23-10.35) for each non-routine release involving the listed substance that occurred during the reporting year. Report on all releases that are equal to or greater than the listed substance's reportable quantity value, RQ, unless the release is federally permitted as defined in 42 U.S.C. 9601, or is specifically excluded under the definition of release as defined in 40 CFR 302.3(22). Reportable quantities are codified in 40 CFR Part 302. If the listed substance is not a hazardous substance under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) and, thus, does not have an RQ, then report releases that exceed 2,270 kg. If such a substance however, is designated as a CERCLA hazardous substance, then report those releases that are equal to or greater than the RQ. The facility may have answered these questions or similar questions under the Agency's Accidental Release Information Program and may already have this information readily available. Assign a number to each release and use this number throughout this part to identify the release. Releases over more than a 24-hour period are not single releases, i.e., the release of a chemical substance equal to or greater than an RQ must be reported as a separate release for each 24-hour period the release exceeds the RQ.

For questions 10.25-10.35, answer the questions for each release identified in question 10.23. Photocopy these questions and complete them separately for each release.

10.01	Where is your facility located? Circle all appropriate responses.
CBI	
[_]	Industrial area
	Urban area
	Residential area
	Agricultural area
	Rural area 5
	Adjacent to a park or a recreational area6
	Within 1 mile of a navigable waterway 7
	Within 1 mile of a school, university, hospital, or nursing home facility
	Within 1 mile of a non-navigable waterway9
	Other (specify)10

	Specify the exact location of your is located) in terms of latitude a (UTM) coordinates.	r facility (from cen and longitude or Uni	versal T	ransvers	e Mercader
	Latitude		037	<u>° 12</u>	47
	Longitude		093	13	, 38
	UTM coordinates Zone	, North	ing	, Ea:	sting
10.03	If you monitor meteorological condithe following information.	ditions in the vicin	ity of y	our faci	lity, provide
	Average annual precipitation	• • • • • • • • • • • • • • • • • • • •	<u> </u>		inches/year
	Predominant wind direction	• • • • • • • • • • • • • • • • • • • •			
10.04	Indicate the depth to groundwater	below your facility	· •		
	Depth to groundwater				meters
10.05 CBI	For each on-site activity listed, listed substance to the environment, N, and NA.)	indicate (Y/N/NA) a	ill routi	ine relea	ses of the
	For each on-site activity listed, listed substance to the environment, N, and NA.)	indicate (Y/N/NA) a nt. (Refer to the i Env	all routi	ine releadions for a	ses of the a definition of
<u>CBI</u>	For each on-site activity listed, listed substance to the environment Y, N, and NA.) On-Site Activity	indicate (Y/N/NA) ant. (Refer to the i	all routi	ine releadions for	ses of the a definition of
<u>CBI</u>	For each on-site activity listed, listed substance to the environment Y, N, and NA.) On-Site Activity Manufacturing	indicate (Y/N/NA) ant. (Refer to the i Env	all routi	ine releadions for a	ses of the a definition of
<u>CBI</u>	For each on-site activity listed, listed substance to the environment Y, N, and NA.) On-Site Activity Manufacturing Importing	indicate (Y/N/NA) ant. (Refer to the i Env Air N/A	all routi	ine releadions for a	ses of the a definition of
<u>CBI</u>	For each on-site activity listed, listed substance to the environment Y, N, and NA.) On-Site Activity Manufacturing	indicate (Y/N/NA) ant. (Refer to the integral Envolution Air N/A N/A Y	all routi	ine releadions for a	ses of the a definition of
<u>CBI</u>	For each on-site activity listed, listed substance to the environment Y, N, and NA.) On-Site Activity Manufacturing Importing Processing	indicate (Y/N/NA) ant. (Refer to the i Env Air N/A	all routi	ine releadions for a	ses of the a definition of
<u>CBI</u>	For each on-site activity listed, listed substance to the environment, N, and NA.) On-Site Activity Manufacturing Importing Processing Otherwise used	indicate (Y/N/NA) ant. (Refer to the int. (Refer to the int. Env. Air. N/A N/A Y N/A N/A	all routi	ine releadions for a	ses of the a definition of
<u>CBI</u>	For each on-site activity listed, listed substance to the environment Y, N, and NA.) On-Site Activity Manufacturing Importing Processing Otherwise used Product or residual storage	indicate (Y/N/NA) ant. (Refer to the int. (Refer to the int.	all routi	ine releadions for a	ses of the a definition of
<u>CBI</u>	For each on-site activity listed, listed substance to the environment Y, N, and NA.) On-Site Activity Manufacturing Importing Processing Otherwise used Product or residual storage Disposal	indicate (Y/N/NA) ant. (Refer to the int. (Refer to the int.	all routi	ine releadions for a	ses of the a definition of
<u>CBI</u>	For each on-site activity listed, listed substance to the environment Y, N, and NA.) On-Site Activity Manufacturing Importing Processing Otherwise used Product or residual storage Disposal	indicate (Y/N/NA) ant. (Refer to the int. (Refer to the int.	all routi	ine releadions for a	ses of the a definition of

10.06	Provide the following information for the listed s of precision for each item. (Refer to the instruction an example.)		
CBI			
[_]	Quantity discharged to the air	44	kg/yr ± UK ;
	Quantity discharged in wastewaters	0	kg/yr ± %
	Quantity managed as other waste in on-site treatment, storage, or disposal units	0	kg/yr ± %
	Quantity managed as other waste in off-site treatment, storage, or disposal units	40	kg/yr <u>+</u> UK 2

[_] Mark (X) this box if you attach a continuation sheet.

0.08 BI	for each process stre	technologies used to minimize release of team containing the listed substance as ideredual treatment block flow diagram(s). Photoately for each process type.	itified in your
_]	Process type	Urethane	
-			
	Stream ID Code	Control Technology	Percent Efficienc
	70, 7P, 7Q	Blower on exit vent to cause more dispersion	N/A
		and TDI reaction with atmospheric moisture	
		•	
			•

10.09 <u>CBI</u> [_]	substance in terms of a St residual treatment block f source. Do not include ra		Identify each emission point source containing the listed ream ID Code as identified in your process block or low diagram(s), and provide a description of each point w material and product storage vents, or fugitive emissiceaks). Photocopy this question and complete it separately		
	Process type	Urethar	ne		
	Point Source ID Code		Description of Emission Point Source		
	70 - 7P - 7Q		Vents to common stack		
			•		
			•		

Mark

 Ξ

this

xoq

]]	Point Source ID Code	Stack Height(m)	Stack Inner Diameter (at outlet) (m)	Exhaust Temperature (°C)	Emission Exit Velocity (m/sec)	Building Height(m)	Building Width(m) ²	Vent Type
	7- 0,P,Q	10.7	0.3	52	UK	18.3	41	vertica
								-
					•			
								
	_		or adjacent	-				
			or adjacent					
	³ Use the	following	codes to des	ignate vent	type:			
	H = Hori V = Veri							

 $[\ \]$ Mark (X) this box if you attach a continuation sheet.

Point source ID code	
This question is N/A. Size Range (microns)	Mass Fraction (% \pm % precision
< 1	·
≥ 1 to < 10	
≥ 10 to < 30	
_ ≥ 30 to < 50	
≥ 50 to < 100	
≥ 100 to < 500	
≥ 500	
- ,	Total = 100%
	·
	•
•	

PART C FUGITIVE EMISSIONS

Equipment Leaks -- Complete the following table by providing the number of equipment types listed which are exposed to the listed substance and which are in service according to the specified weight percent of the listed substance passing through the component. Do this for each process type identified in your process block or residual treatment block flow diagram(s). Do not include equipment types that are not exposed to the listed substance. If this is a batch or intermittently operated process, give an overall percentage of time per year that the process type is exposed to the listed substance. Photocopy this question and complete it separately for each process type.

[-]	Process type	Urethane		_
	Percentage of time	per year that	the listed substance is exposed to this process	%

	Number	of Compor	ents in	Service by	y Weight	Percent
		of Lister	l Substan	ce in Pro	cess Stre	Creater
	Less	F 108/	11 25%	26 75%	76-99%	Greater than 99%
Equipment Type	than 5%	<u>5-10%</u>	11-25%	<u>26-75%</u>	70-33%	Chan 55%
Pump seals ¹						A1 / B
Packed	N/A	N/A 	N/A	N/A	N/A 	N/A
Mechanical	N/A	N/A	N/A	<u> N/A</u>	N/A	4 *
Double mechanical ²	N/A	N/A	N/A	N/A	N/A	N/A
Compressor seals ¹	N/A	N/A	N/A	N/A	N/A	N/A
Flanges	N/A	N/A	N/A	N/A	N/A	4.
Valves						
Gas ³	2 -	N/A	N/A	N/A	N/A	N/A
Liquid	N/A	N/A	N/A	_N/A	<u>N/A</u>	4
Pressure relief devices ⁴ (Gas or vapor only)	N/A	N/A	N/A	<u>N/A</u>	<u>N/A</u>	N/A
Sample connections						
Gas	N/A	N/A	N/A	_N/A	N/A	N/A
Liquid	N/A	N/A	N/A	N/A	N/A	N/A
Open-ended lines ⁵ (e.g., purge, vent)						
Gas	N/A	N/A	_N/A	N/A	N/A	<u>N/A</u>
Liquid	N/A	N/A	N/A	N/A	N/A	N/A

List the number of pump and compressor seals, rather than the number of pumps or compressors

* Flanges act as seals. Pump contains no seals that contain listed substance.

[] Mark (X) this box if you attach a continuation sheet.

10.13

(continued)												
² If double mechanical seals are operated with the barrier (B) fluid at a pressure greater than the pump stuffing box pressure and/or equipped with a sensor (S) that will detect failure of the seal system, the barrier fluid system, or both, indicate with a "B" and/or an "S", respectively ³ Conditions existing in the valve during normal operation ⁴ Report all pressure relief devices in service, including those equipped with control devices												
									⁵ Lines closed during normal operations	l operation that wou	ld be used during	maintenance
									pressure relief devices ide devices in service are con	entified in 10.13 to trolled. If a press	indicate which pr	ressure rellet
а.	b.	c.	d.									
Number of Pressure Relief Devices	Percent Chemical in Vessel	Control Device	Estimated Control Efficiency									
This question	is N/A.											
		_										
heading entitled "Number o	f Components in Serv	d the percent rang vice by Weight Per	ge given under the cent of Listed									
with runture discs under n	ormal operating cond	litions. The EPA $lpha$	assigns a control									
	2 If double mechanical seals greater than the pump sturwill detect failure of the with a "B" and/or an "S", 3 Conditions existing in the Report all pressure relies control devices 5 Lines closed during normal operations Pressure Relief Devices wi pressure relief devices id devices in service are conenter "None" under column a. Number of Pressure Relief Devices This question 1 Refer to the table in question has beading entitled "Number of Pressure Relief Devices This question 2 The EPA assigns a control with runture discs under no with runture discs under no with runture discs under no pressure relief properties and the runture discs under no pressure relief properties and the runture discs under no pressure relief properties and the runture discs under no pressure relief properties and the runture discs under no pressure relief properties and the runture discs under no pressure relief properties and the runture discs under no pressure relief properties and the runture discs under no pressure relief properties are control with runture discs under no pressure relief properties and the runture discs under no pressure relief properties are control pressure relief properties are control pressure relief pres	2 If double mechanical seals are operated with greater than the pump stuffing box pressure a will detect failure of the seal system, the b with a "B" and/or an "S", respectively 3 Conditions existing in the valve during normal 4 Report all pressure relief devices in service control devices 5 Lines closed during normal operation that wou operations Pressure Relief Devices with Controls Compl pressure relief devices identified in 10.13 to devices in service are controlled. If a pressenter "None" under column c. a. Number of Percent Chemical in Vessel This question is N/A. 1 Refer to the table in question 10.13 and recombed in the service of the servi	2 If double mechanical seals are operated with the barrier (B) fi greater than the pump stuffing box pressure and/or equipped wit will detect failure of the seal system, the barrier fluid system with a "B" and/or an "S", respectively 3 Conditions existing in the valve during normal operation 4 Report all pressure relief devices in service, including those control devices 5 Lines closed during normal operation that would be used during operations Pressure Relief Devices with Controls Complete the following pressure relief devices identified in 10.13 to indicate which produces in service are controlled. If a pressure relief device enter "None" under column c. a. b. c. Number of Percent Chemical in Vessel Control Device This question is N/A. 1 Refer to the table in question 10.13 and record the percent range heading entitled "Number of Components in Service by Weight Percent Components in Service by									

Process type	• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • • •	<u>Urethan</u> e		and the same of th
Equipment Type	Leak Detection Concentration (ppm or mg/m³) Measured at Inches from Source	Detection Device	Frequency of Leak Detection (per year)	Repairs Initiated (days after detection)	Repairs Complete (days aft initiated
Pump seals Packed	This question is	N/A.			
Mechanical Double mechanical					
Compressor seals Flanges					
Valves Gas					
Liquid					
Pressure relief devices (gas or vapor only)					
Sample connections					
Gas	-				121 11 121
Liquid Open-ended lines	140 1 · · ·	-	-		
Gas Liquid					
 ¹ Use the following co	_		evice:		
FPM = Fixed point m 0 = Other (specify)	onitoring				

CBI	01 103	iddii tid	atment block			Versel	Veccel		Operat- ing	-				
]	Vessel Type		Composition of Stored Materials	(liters	Rate	Filling	Vessel Inner Diameter (m)	Vessel Height (m)	Vessel Volume	Vessel Emission Controls	Flow	Vent Diameter (cm)	Control Efficiency (%)	Basis for Estimate
		This qu	uestion is N	/ <u>A.</u>		·								
								-						
							· · · · · · · · · · · · · · · · · · ·							•
								_	-		-			
	F CIF NCIF EFR P H U	= Fixed r = Contact = Noncont = Externa = Pressur = Horizor = Undergr	internal flact internal al floating revessel (internal cound	coating roof floating ro coof ndicate press	of are ratio	ng)	MS: MS: LM LM LM VM VM	1 = Med 2 = Sho 2R = Rin 1 = Lid 2 = Rin W = Wed 1 = Va 2 = Rin W = Wed	chanical oe-mount m-mount quid-mou m-mount ather si por mou m-mount ather si	I shoe, prited secondard, secondard resiled shield inted resiled secondard hield	imary ary ary lient fi ient fi ry	illed seal lled seal,	primary	s:
	F CIF NCIF EFR P H U	= Fixed r = Contact = Noncont = Externa = Pressur = Horizor = Undergr	roof internal fluct internal al floating revessel (in ntal round	coating roof floating ro coof ndicate press	of are ratio	ng)	MS: MS: LM LM LM VM VM	1 = Med 2 = Sho 2R = Rin 1 = Lid 2 = Rin W = Wed 1 = Va 2 = Rin W = Wed	chanical oe-mount m-mount quid-mou m-mount ather si por mou m-mount ather si	I shoe, prited secondard, secondard resiled shield inted resiled secondard hield	imary ary ary lient fi ient fi ry	illed seal lled seal,	, primary primary	s:
	F CIF NCIF EFR P H U	= Fixed r = Contact = Noncont = Externa = Pressur = Horizor = Undergr	coof internal fluction internal internal floating revessel (internal cound internal floating revessel (internal cound internal floating round internal floating roofs	coating roof floating ro coof ndicate press	of nure ration	ng) e. Includ	MS: MS: LM: LM: VM VM VM	1 = Med 2 = Sho 2R = Rin 1 = Lid 2 = Rin W = Wed 1 = Va 2 = Rin W = Wed	chanical oe-mount m-mount quid-mount ather sl por moun m-mount ather si ather si	I shoe, proted secondary secondary inted residented hield need secondary inted ganic cont	imary ary ary lient fi ient fi ry ent in	illed seal, lled seal, parenthesi	, primary primary	s:
	F CIF NCIF EFR P H U	= Fixed r = Contact = Noncont = Externa = Pressur = Horizor = Undergr cate weight r than flow	roof internal fluct internal al floating revessel (in ntal round	coating roof I floating ro roof roof rdicate press f the listed	of wure ration substance	ng) e. Includ e was desi	MS: MS: LM: LM: VM: VM: VM: le the tot	1 = Mee 2 = Sho 2R = Rin 1 = Lio 2 = Rin W = Wea 2 = Rin W = Wea al vola	chanical oe-mount m-mount quid-mount ather si por moun m-mount ather si tile or specify	I shoe, proted secondary secondary inted residented hield need secondary inted ganic cont	imary ary ary lient fi ient fi ry ent in	illed seal, lled seal, parenthesi	, primary primary	s:

10.23	was stopped list all	ed. If there w	were more than	six releases,	d and when the re attach a continu	ation sheet and
	Release		ate arted	Time (am/pm)	Date Stopped	Time (am/pm)
	1	None	5	N/A	N/A	N/A
	2					.
	3			·		-
	4			-,		
	5					
	6					
	<u>Release</u> <u>1</u> 2	Wind Speed (km/hr)	Direction		(°C)	(Y/N)
	3					
	3 4					
	4					
	4					
	4					
	4					
	4					

General Offices/3M

3M Center St. Paul, Minnesota 55101-1000

DOCUMENT PROCESSING CENTER
OFFICE OF TOXIC SUBSTANCES, TS-790
U.S. EPA
401 M ST., SW
WASHINGTON, D.C. 20460
A tim. CAIR Report Office

